

UNIT G-21						
Date	hrs	Description	Parts	Labour	Notes	Supporting Documents
June 21, 2014	22,329	tire change over	\$ 1,820.20			Kal Tire 087820911
June 29, 2014		trouble shoot not charging, new Alternator	\$ 2,975.73	\$ 500.00	see repair reports	Finning 942678944
July 16, 2014		trouble shoot steering system	\$ 3,656.05	\$ 800.00	see repair reports	Finning 942716976
July 24, 2014		replace secondary steering motor	\$ 2,016.18	\$ 400.00	see repair reports	Finning 942734478
July 31, 2016	22,695	wear strips	\$ 5,000.61			Finning 942750838
August 2, 2014	22,724	plates	\$ 2,493.89			Finning 942754924
August 6, 2014		wear strips and plates	\$ 10,303.69			Finning 942759791
September 6, 2014	22,979	sup steering electric motor	\$ 1,926.41			Finning 942825770
September 28, 2014	23,190	fan assembly	\$ 658.97			Finning 942872547
November 16, 2014	23,748	change edges		\$ 250.00	see repair reports	
April 14, 2015	24,273	remove and install diff pinion	\$ 7,139.09	\$ 1,050.00	see repair reports	Finning 94326795
May 1, 2015	24,594	remove tranny		\$ 1,250.00	see repair reports	
May 6, 2015	24,594	transmission gear pump	\$ 9,073.89			Finning 943313338
May 6, 2015	24,594	gear planet final drive	\$ 3,343.98			Finning 943312340
May 6, 2015	24,594	oil cooler	\$ 1,638.04			Finning 943312454
May 6, 2015	24,594	remove oil pan, roll in engine bearings, rods and main,install oil pump, oil pan, trans cooler		\$ 2,100.00	see repair reports	
May 8, 2015	24,594	trans pump	\$ 4,126.50			Finning 943316839
May 11, 2015	24,594	pump-gp-ps-b	\$ 3,137.54			Finning 943320372
May 11, 2015	24,594	gears and drum	\$ 4,116.00			Finning 943320950
May 11, 2015	24,594	install rebuilt trans and diff		\$ 1,050.00	see repair reports	
May 13, 2015	24,594	driveshaft	\$ 1,141.57			Pat's Driveline 2283941-00
May 14, 2015	24,594	sensor, valve	\$ 1,930.98			Finning 943328851
May 14, 2015	24,594	circle drive pinion	\$ 814.88			Finning 943328277
May 23, 2015	24,594	circle drive shaft	\$ 2,087.10			Finning 943344261
May 23, 2015	24,594	replace main circle drive shaft		\$ 650.00	see repair reports	
May 30, 2015	24,594	change edges		\$ 250.00	see repair reports	
			\$ 69,401.30	\$ 8,300.00		
			Total Cost	\$ 77,701.30		