

Equipment:	2009 Cat 16M Grader						TOTAL COST OF REPAIR (US\$)	\$	134,594.43			
Equipment No.:	G-18						Direct Material Cost		89767.14			
Serial No.:	B9H00668						Shop Material Cost					
							Labor Cost		44827.29			
	work done in Irvine, CA											
Work Description		Machine Hours	Cost (US\$)	Supplier	Invoice Number	Date	Labor Cost	Remarks				
			460.00	Absolute Glass	412	2014-04-25						
			458.65	Napa	122404	2014-04-25						
			104.88	Quinn	662734	2014-05-14	8411.74					
			1454.7	Quinn	830303313	2014-05-14	11325.74	bearings, washers				
			609.49	Quinn	830303471	2014-05-14		seals, clamps, hose				
			109.41	Quinn	830303472	2014-05-14						
			24.82	Quinn	830303473	2014-05-14						
			84.3	Quinn	830303532	2014-05-14						
			98.13	Quinn	830303534	2014-05-14						
			75.65	Quinn	830303601	2014-05-14						
			939.12	Quinn	830303669	2014-05-14		seals, nuts, shim, ring				
			4956.66	Quinn	830303757	2014-05-14		seals, tubes, bushing, washer				
			1920.02	Quinn	830303758	2014-05-14		seals, tubes, bushing, washer				
			1451.23	Quinn	830303759	2014-05-14		collar, pinion, bearing				
			393.2	Quinn	830303761	2014-05-14						
			182.78	Quinn	830303763	2014-05-14						
			109.54	Quinn	830303764	2014-05-14						
			230.54	Quinn	830303821	2014-05-14						
			335.54	Quinn	830303826	2014-05-14						
			54.58	Quinn	830303827	2014-05-14						
			1819.81	Quinn	830303828	2014-05-14		core				
			10.56	Quinn	830303830	2014-05-14						
			20.75	Quinn	830303905	2014-05-14						
			195.35	Quinn	830303942	2014-05-14						
			708.85	Quinn	830303994	2014-05-14		seals, rings,				
			1276.8	Manganal Sales	96939	2014-05-15						
			-90	Napa	277090	2014-05-15						
			33.24	Napa	255960	2014-05-15						
			146.53	Napa	254480	2014-05-15						
			373.05	Regal Corporation	1349307	2014-05-15	755.94					
			50889.94	Sonsray Machinery	2160	2014-05-30		GPS install				
			14.58	Quinn	830304181	2014-05-30						
			13.8	Quinn	830304236	2014-05-30						
			42.06	Quinn	830304701	2014-05-30						
			729	J.D. Labine	2518	2014-06-09	3136.59					
		Subtotal=	70237.56			Subtotal =	23630.01					
Work Description		Machine Hours	Cost (US\$)	Supplier	Invoice Number	Date	Labor Hours	Remarks				
			-517.85	Quinn	208475	2014-06-30	1393.49					
			901.50	Visa		2014-07-02	404.31					
			1178.80	J.D. Labine	2525	2014-12-31						
			668.8	J.D. Labine	2527	2014-12-31						
			4888.98	Quinn	830318527	2015-07-02		kit gasket, shaft, bearing				
			1646.05	Quinn	830318656	2015-07-02		shaft				
			7173.06	Quinn	830322401	2015-09-02		shaft, gear				
			24	Napa	309198	2016-12-22						

		795.02	Quinn	830340795	2016-12-22		shim, kit seal
		1203.7	Quinn	830340899	2016-12-22		seals, bearings,washers
		559.6	Quinn	830340935	2016-12-22		washer,retainer
		55.75	Quinn	830341062	2016-12-22		
		-140.45	Quinn	830212098	2016-12-22	16890.24	
repaired fuel leak,	26,437	185.72	Johnson Machinery	1435619	2017-01-03		
replaced fuel pump		630.39	Johnson Machinery	1436091	2017-01-03		
resealed r/s lift cyl		36.34	Quinn	830341022	2017-01-03		
resealed l/s lift cylinder		101.84	Quinn	830341183	2017-01-03		
resealed ripper cyl		-214.76	Quinn	830212142	2017-01-03		
replaced slide inserts		64.98	Quinn	830341290	2017-01-03		
adjusted cilcle drive wear pads		-86.56	Quinn	830212168	2017-01-03		
repaired electrical & clear all active codes		374.67	Paint		2017-01-03		
repaired both sides steering cyl pin boss					2017-02-28	2509.24	
replaced both sides steering cyl bearings & l/s pin							
repaired both sides steering spindle pin boss							
replaced both sides steering spindle pins & bearings							
replaced center shift inserts							
resealed rear housing cover plate							
changed engine oil & filter							
changed fuel filters							
changed pri-sec a/f							
resealed l/s tandem							
replaced 2 valve solenoid coil assembly for blade cushion							
	Subtotal=	19529.58			Subtotal =	21197.28	